

Machinist III

JOB SUMMARY

This position is responsible for the machining required by work orders, including but not limited to the set up, production, and inspection of all machining and/or shop assembly jobs assigned by Shop Supervisor. Machinist III is required to follow all StoneAge safety guidelines to produce parts that will meet or exceed StoneAge and customer specifications.

This position reports to the Shop Supervisor.

ESSENTIAL FUNCTIONS

- Complete assigned work orders that require machining or assembly.
- Complete 1st article inspection on all orders.
- Complete daily maintenance on machines; continually keep a neat workspace, store tools when not in use and keep shop clean.
- Follow proper paperwork procedures.
- Communicate time off requests, as well as personnel and shop maintenance issues to the Shop Supervisor.
- Perform other duties required or requested by Shop Supervisor.

KNOWLEDGE AND TRAINING REQUIREMENTS

The Machinist III must:

- Be able to setup, program and operate Mills, Lathes and CNC machines.
- Be proficient at manual machining, able to machine very complex parts.
- Be knowledgeable with external CAM programs (ex: Virtual Gibbs).
- Perform tasks assigned by Shop Supervisor with little to no supervision, guidance, or quality issues.
- Observe and listen to operating machines or equipment to diagnose machine malfunctions and to determine need for adjustments or repairs.
- Read and interpret engineering prints, work orders and customer orders.
- Be a team player and work with others in problem solving, including but not limited to shop team, engineering, sales, and production.
- Always strive to produce quality work.
- Mechanically inclined and trainable.
- Able to use small tools and gage parts
- Assist in training Machinist I & II shop team members.

OTHER INFORMATION

- Must be able to stand for extended periods of time.
- Must be able to lift heavy loads using proper lifting techniques as outlined in the StoneAge Employee Handbook.