

# BARRACUDA, GOPHER, SL NEW CARTRIDGE ASSEMBLY

A design change has been made to the cartridge of the BC-H9-C Barracuda to improve the seal life. The new cartridge part number is BC 505, which replaces the BC 405 and SL 405 cartridges. The BC 602-H9-C seal kit replaces the SL 602-H9-C seal kit. The cartridge assembly is interchangeable with all the existing Barracudas, Gophers and SL swivels that use the cartridge, but the internal parts of the cartridge have changed. The Housing (BC 407) and the O-Ring (BJ 072) are the same. None of the other parts are interchangeable- refer to the exploded views below comparing the cartridges and be sure to use the correct part number for the new parts, assemblies and kits. Externally, the cartridge assemblies can be distinguished by pushing on the seat face; the old cartridge is spring loaded and the seat face will spring out, while the new one does not. When replacing the cartridge, inspect the end of the shaft in the swivel for damage such as galling or erosion- we recommend replacing damaged shafts. All kits include either the complete new cartridge or all the parts needed to rebuild the cartridge.

